

CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-9124

 Web:
 www.stpaul.gov/dsi

Code Compliance Report

August 04, 2009

HOUSING AND REDEVELOPMENT 25 W 4TH ST STE 1300 ST PAUL MN 55102

Re: 275 Bates Ave File#: 06 092130 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on July 23, 2009.

Please be advised that this report is accurate and correct as of the date August 04, 2009. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from August 04, 2009. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

BUILDING Inspector: Ken Eggers Phone: 651-266-9047

- Insure basement cellar floor is even, cleanable and all holes are filled
- Install plinth blocks under posts in basement
- Tuck Point interior/exterior of foundation as necessary
- Dry out basement and eliminate source of moisture
- Remove mold, mildew and moldy or water damaged materials
- Permanently secure top and bottom of support posts in an approved manner
- Install handrails and guardrails at all stairways, including basement stairways, and return handrail ends to the wall or newel post per attachment.
- Strap or support top of stair stringers
- Install tempered or safety glass in window over stair landing to code
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary
- Provide complete storms and screens, in good repair for all door and window openings
- Provide and operable latching device for all windows
- Provide thumb type deadbolts for all entry doors. Remove any surface bolts
- Repair or replace damaged doors and frames as necessary, including storm doors
- Weather seal exterior doors

- Install floor covering in bathroom and kitchen that is impervious to water
- Repair walls, ceiling and floors throughout, as necessary
- Provide fire block construction as necessary
- Where wall and ceiling covering is removed install full thickness or code-specified insulation
- Install attic insulation according to applicable code
- Air-seal and insulate attic access door in an approved manner
- Provide smoke detectors per the MN Building Code and carbon monoxide detectors per State Law.
- Replace or repair landing and stairway per code
- Repair siding, soffit, fascia, trim, etc. as necessary
- Provide proper drainage around house to direct water away from foundation of house.
- Close in open stair risers to maintain an opening no greater than 4 inches
- A building permit is required to correct the above deficiencies
- Remove stacked blocks under support posts in basement and provide posts going from footing to support beam.
- Clean basement foundation walls and tuckpoint and re-parge.
- Repair basement stairs and re-level.
- Repair or replace kitchen cabinets.
- Refinish wood floors, replace floor coverings.
- Repair or replace retaining wall at West side of property.
- Remove trees on west side, trees are rubbing on structure.
- This property is being converted to a Single Family Dwelling.

ELECTRICAL Inspector: Jamie McNamara Phone: 651-266-9037

- Provide a complete circuit directory at service panel indicating location and use of all circuits
- verify/install a separate 20 ampere laundry circuit and a separate 20 ampere kitchen appliance circuit
- Close openings in service panel/junction box with knock out seals, breaker blanks and/or junction boxes
- Properly strap cables and conduits in basement/ service conduit on the exterior of the house.
- install/replace GFCI receptacle in basement/first/second bathroom adjacent to the sink
- Ground bathroom light in basement/first bathroom/second bathroom and disconnect receptacle on fixture
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Remove any 3-wire ungrounded outlets and replace with 2-wire or ground 3-wire to code
- Install hard-wired, battery backup smoke detector per bulletin 80-1 and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms
- Install exterior lights at front/side entry doors
- Basement rewire furnace to code.

- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the 2008 NEC.
- All buildings on the property must meet the St. Paul Property Maintenance Code (Bulletin 80-1).

PLUMBING Inspector: Denny Watters Phone: 651-266-9051

- Basement Laundry Tub faucet is missing
- Basement Laundry Tub unvented
- Basement Soil and Waste Piping no front sewer clean out; no soil stack base clean out
- Basement Soil and Waste Piping no soil stack base clean out
- Basement Soil and Waste Piping unplugged or open piping; back pitched piping
- Basement Water Heater No gas shut off or gas piping incorrect
- Basement Water Heater Vent must be in chimney liner
- Basement Water Heater not fired or in service
- Basement Water Meter Remove steel from before meter
- Basement Water Meter meter is removed or not in service
- Exterior Lawn Hydrants Requires backflow assembly or device
- First Floor Gas Piping range gas shut off; connector or piping incorrect
- First Floor Lavatory unvented
- First Floor Sink fixture is missing
- First Floor Tub and Shower provide stopper
- Second Floor Gas Piping range gas shut off; connector or piping incorrect
- Second Floor Lavatory incorrectly vented
- Second Floor Lavatory waste incorrect
- Second Floor Sink waste incorrect
- Second Floor Tub and Shower unvented
- Second Floor Tub and Shower waste incorrect

HEATING Inspector: Maureen Hanson Phone: 651-266-9043

- Clean and Orsat test furnace burner. Check all controls for proper operation. Check furnace heat exchanger for leaks; provide documentation from a licensed contractor that the heating unit is safe.
- Install approved metal chimney liner.
- Connect furnace and water heater venting into chimney liner.
- Vent clothes dryer to code.
- Provide adequate combustion air and support duct to code.
- Provide support for gas lines to code. Plug, cap and/or remove all disconnected gas lines.
- Witnessed air test on new gas piping to furnace.
- Provide appropriate size openable window in all bathrooms or prove approved bathroom exhaust fan is vented to the exterior (Ventilation permit maybe required).
- Install furnace air filter access cover.

- Clean all supply and return ducts for warm air heating system.
- Provide dampers in all supply runs.
- Repair and/or replace heating registers as necessary.
- Provide heat in every habitable room and bathrooms.
- Mechanical GAS permit is required for the above work and possible a Venation permit also.

Possible a furnace is in the attic – verify it is installed to code and provide access for inspection.

ZONING

1. This property was inspected as a Single Family Dwelling.

Notes:

- See attachment for permit requirements and appeals procedure.
- Most of the roof covering could not be inspected from grade. Recommend this be done before rehabilitation is attempted.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Ken Eggers between 7:30 - 9:00 AM at 651-266-8989 or leave a voice mail message.

Sincerely,

James L. Seeger Code Compliance Officer JLS:ml Attachments